

## LOCKHART FIRE

**31<sup>st</sup> May 2018**

Dear Members & Clerks,

You will all be aware of the fire that occurred on the scaffold at Lockhart Chambers this morning, for your information, I can advise the following:

- The fire was contained to the scaffold;
- The fire investigators are currently investigating the ignition point; their current theory is the most likely cause is faulty electrical appliance but investigations are ongoing;
- All of the old flammable cladding was fortunately completely removed last week;
- There were no hot-works taking place this morning, the builders who were on-site when the fire started were pinning the old cladding, painting on the waterproofing and sealing the windows with silicone;
- The fire looked much worse than it actually was and the reason it spread so quickly was because of the flammable mesh that surrounded the scaffold, the fire investigators advised CCL staff that this was the same issue they had at a recent fire in Circular Quay and they have been dealing with the authorities to have it banned. The Builders have subsequently produced certification documentation for the mesh and the scaffolding, the installation of the mesh was a Council requirement;
- There are a couple of cracked windows on levels 11 & 12 but apart from that there is no damage to the internal of the building and the building structure. CCL's structural engineers and fire engineers have been engaged to come to site for a final sign off later today;
- The entrance to Lockhart Chambers remains closed for the moment but we expect it to re-open within a couple of hours;
- Members can gain entrance to their Chambers through the Phillip Street entrance on Level 1, the fire brigade cleared the building for re-occupation around 9am;
- Macquarie Street is currently opening (in stages) and the fire brigade have formally handed the site back to CCL;
- The Builders are currently cleaning up the site now;
- The existing scaffold does not need to be removed as the damage was very limited, there will need be some repairs but work will progress on the Lockhart façade as soon as the scaffold has been cleaned and repaired;
- All of the fire alarms and EWIS for the buildings worked as they should and the building was immediately evacuated and CCL were quickly able to identify from the access logs who was in the building and also from our contractor on-site software who was on the scaffold so everyone was quickly accounted for. None of the sprinklers were activated.

Please let me know if you require any further information.

Kind regards,

**Debbie George**  
General Manager

COUNSEL'S  
CHAMBERS  
LIMITED

Level 1 Selborne Chambers  
174 Phillip Street Sydney  
NSW 2000 Australia  
DX 973 Sydney

**P:** +61 2 9231 3644

**E:** [dgeorge@ccl.com.au](mailto:dgeorge@ccl.com.au)

**W:** [www.ccl.com.au](http://www.ccl.com.au)

This email (including any attachments) is confidential, may be privileged, may contain commercially valuable information and intended solely for the use of the individual or entity to whom it is addressed. It may be read, copied and used only by the intended recipient. If you have received it in error, please contact CCL on +61 2 9231 3644 or by email at [admin@ccl.com.au](mailto:admin@ccl.com.au), or the Sender immediately by return email, and immediately delete this email. CCL reserves the right to monitor all email communications through its networks. If the content of this email is personal or unconnected with CCL's business, we accept no liability or responsibility for it. You should take full responsibility for virus checking of this email and any attachments. If this email contains personal information (as defined in the Privacy Act Cth as amended) you must at all times comply with the Privacy Act and Australian Privacy Principles in connection with the personal information.